

AVH-X5600BHS and AVH-X3600BHS Firmware Update for SiriusXM Users

February 17, 2014

Dear Valued Pioneer Customer:

We would like to inform you of the availability of a free firmware update (version 08.05) for the Pioneer AVH-X5600BHS and AVH-X3600BHS DVD Receivers. This firmware update applies only to AVH-X5600BHS and AVH-X3600BHS units sold in the United States and Canada. This update (version 08.05) contains the following improvement:

- Resolves SiriusXM audio dropout issues when the Pioneer DVD Receiver is connected to a SiriusXM SXV200 tuner.

This notice explains how to obtain the free firmware update for the AVH-X5600BHS and AVH-X3600BHS.

HOW TO OBTAIN THE FREE FIRMWARE UPDATE:

1. Download the firmware update files to a computer from the Pioneer website: www.pioneerelectronics.com/downloads
2. Transfer the files to a USB storage device for connection to the Pioneer AVH-X5600BHS and AVH-X3600BHS DVD Receiver.

Questions?

If you have any questions, please contact Pioneer Customer Service toll free at 1-800-421-1404. Pioneer service representatives are available Monday through Friday, 10:30 AM - 2:30 PM and 3:30 PM - 7:00 PM (Eastern Time), except on holidays.

Sincerely,

Pioneer Electronics (USA) Inc.