



## **Firmware Update (version A860) for CD Receivers and Digital Media Receiver**

October 21, 2014

**Dear Valued Pioneer Customer:**

We would like to inform you of the availability of a firmware update (version A860) for the following Pioneer CD Receiver and Digital Media Receiver models: DEH-X6700BS, DEH-X6700BT, DEH-X6710BT, DEH-X4700BT, MVH-X370BT, FH-X720BT, and FH-X721BT. **This update is only for the preceding models, sold in the United States and Canada. Installation on any other product could cause irreversible damage.**

The update resolves an issue receiving calls when an incoming call has caller ID blocked. Please visit [pioneerelectronics.com/firmware](http://pioneerelectronics.com/firmware) for instructions on downloading and installing the update.

### **Questions**

If you have any questions, please contact Pioneer Customer Service toll free at 1-800-421-1404, Monday through Friday, 10:30 AM - 2:30 PM and 3:30 PM - 7:00 PM (Eastern Time), excluding holidays, or by email through [parts.pioneerelectronics.com/contact/](mailto:parts.pioneerelectronics.com/contact/).

Sincerely,

**Pioneer Electronics (USA) Inc.**